






Helical worm gear units S





Type of construction





Foot mounted version
Hollow shaft with keyway
Example: S32A DM90L4





Foot mounted version
Output shaft with key
Example: S12AV DM80G4





Shaft mounted version
Hollow shaft with keyway
Example: S22B DM100L4





Shaft mounted version
Hollow shaft with shrink disc
Torque arm T1
Example: S22**B**T1**S** DM80K4





Flange mounted version
Hollow shaft with keyway
Example: S22**C** DM90S4





Flange mounted version
Output shaft with key
Example: S12**C**V DM71G4



Flange mounted version
Hollow shaft with shrink disc
Example: S32**C**S DM100LX4



Shaft mounted version + foot area
Hollow shaft with keyway
Example: S22**D** DM80G4



Flange mounted version + foot area
Hollow shaft with keyway
Example: S32**E** DM90S4

Selection table - Gear units

i	T2max [Nm]	P1max [kW]	TA3 TA32 TA33 TA4 TA42 TA43 TA5 TA52 TA53 TA6 TA62 TA63 W1 -W2 -W3 -W4 -W5
---	---------------	---------------	--

S02

189.00	58	0.10	- - - - -
159.35	58	0.11	- - - - -
135.95	57	0.12	- - - - -
117.00	56	0.14	○ - - - -
101.35	55	0.15	○ - - - -
88.20	53	0.16	○ - - - -
77.00	52	0.18	○ - - - -
69.00	69	0.21	○ - - - -
58.18	67	0.24	○ - - - -
49.63	66	0.27	○ - - - -
42.71	64	0.30	○ - - - -
37.00	62	0.34	○ - - - -
32.20	60	0.37	○ - - - -
28.11	58	0.41	○ - - - -
25.00	63	0.44	○ - - - -
21.08	61	0.50	○ - - - -
17.98	59	0.56	○ - - - -
15.48	57	0.63	○ - - - -
13.41	55	0.70	○ - - - -
12.50	67	0.75	○ - - - -
11.67	53	0.75	○ - - - -
10.54	65	0.75	○ - - - -
10.19	51	0.75	○ - - - -
8.99	63	0.75	○ - - - -
7.74	61	0.75	○ - - - -
6.70	59	0.75	○ - - - -
5.83	57	0.75	○ - - - -
5.09	55	0.75	○ - - - -

S12G03

9007.5	188	<0.05	○ - - - - -
7609.6	188	<0.05	○ - - - - -
6505.9	188	<0.05	○ - - - - -
5612.6	188	<0.05	○ - - - - -
4874.5	188	<0.05	○ - - - - -
4254.6	188	<0.05	○ - - - - -
3672.3	188	<0.05	○ - - - - -
3168.0	188	<0.05	○ - - - - -
2751.5	187	<0.05	○ - - - - -
2401.5	187	<0.05	○ - - - - -

S12G02

2108.1	187	<0.05	○ - - - - -
1781.0	187	<0.05	○ - - - - -
1522.7	186	<0.05	○ - - - - -
1313.6	186	<0.05	○ - - - - -
1140.8	186	0.05	○ - - - - -
995.75	185	0.06	○ - - - - -
872.16	185	0.07	○ - - - - -
749.62	184	0.08	○ - - - - -
646.68	184	0.09	○ - - - - -
561.65	183	0.10	○ - - - - -
490.22	182	0.11	○ - - - - -
429.37	181	0.12	○ - - - - -
375.31	180	0.14	○ - - - - -
330.65	179	0.15	○ - - - - -
293.14	178	0.17	○ - - - - -
261.18	177	0.18	○ - - - - -
234.46	176	0.20	○ - - - - -
204.64	174	0.22	○ - - - - -
179.24	172	0.25	○ - - - - -

i	T2max [Nm]	P1max [kW]	TA3 TA32 TA33 TA4 TA42 TA43 TA5 TA52 TA53 TA6 TA62 TA63 W1 -W2 -W3 -W4 -W5
---	---------------	---------------	--

S12

168.00	171	0.26	○ - - - - -
143.53	168	0.29	○ - - - - -
124.21	165	0.32	○ ○ - - - -
108.57	162	0.35	○ ○ ○ - - - -
95.65	160	0.39	○ ○ ○ - - - -
84.80	157	0.42	○ ○ ○ - - - -
75.56	153	0.46	○ ○ ○ - - - -
67.83	150	0.49	○ ○ ○ - - - -
60.90	166	0.5	○ - - - - -
59.20	146	0.54	○ ○ ○ - - - -
52.03	163	0.59	○ - - - - -
51.85	141	0.59	○ ○ ○ - - - -
45.03	160	0.66	○ ○ ○ - - - -
39.36	156	0.73	○ ○ ○ - - - -
34.67	153	0.80	○ ○ ○ - - - -
30.74	150	0.88	○ ○ ○ - - - -
27.39	146	0.96	○ ○ ○ - - - -
24.59	143	1.04	○ ○ ○ - - - -
22.68	152	1.12	○ - - - - -
21.46	138	1.14	○ ○ ○ - - - -
19.38	149	1.27	○ - - - - -
18.80	133	1.25	○ ○ ○ - - - -
16.77	146	1.43	○ ○ ○ - - - -
14.66	142	1.50	○ ○ ○ - - - -
12.91	139	1.50	○ ○ ○ - - - -
11.45	136	1.50	○ ○ ○ - - - -
10.20	132	1.50	○ ○ ○ - - - -
9.16	129	1.50	○ ○ ○ - - - -
7.99	124	1.50	○ ○ ○ - - - -
7.00	120	1.50	○ ○ ○ - - - -

S22G13

13901	340	<0.05	○ - - - - -
11784	340	<0.05	○ - - - - -
10114	340	<0.05	○ - - - - -
8761.0	340	<0.05	○ - - - - -
7643.7	340	<0.05	○ - - - - -
6705.1	340	<0.05	○ - - - - -
5905.6	340	<0.05	○ - - - - -
5193.0	340	<0.05	○ - - - - -
4456.7	340	<0.05	○ - - - - -
3860.7	340	<0.05	○ - - - - -
3368.3	340	<0.05	○ - - - - -

i	T2max [Nm]	P1max [kW]	TA31 TA32 TA33 TA41 TA42 TA43 TA51 TA52 TA53 TA61 TA62 TA63	-W1 -W2 -W3 -W4 -W5
---	---------------	---------------	--	---------------------------------

S22G12

2998.2	340	<0.05	○ - - - - -	○ - - - -
2561.5	340	<0.05	○ - - - - -	○ - - - -
2216.7	340	<0.05	○ - - - - -	○ ○ - - -
1937.6	340	0.05	○ - - - - -	○ ○ - - -
1707.1	340	0.06	○ - - - - -	○ ○ - - -
1513.4	335	0.07	○ - - - - -	○ ○ - - -
1348.4	335	0.07	○ - - - - -	○ ○ - - -
1210.5	335	0.08	○ - - - - -	○ ○ - - -
1056.5	335	0.09	○ - - - - -	○ ○ - - -
925.37	335	0.10	○ - - - - -	○ ○ - - -
850.54	335	0.11	○ - - - - -	○ ○ - - -
749.33	335	0.12	○ - - - - -	○ ○ - - -
664.32	330	0.14	○ - - - - -	○ ○ - - -
591.90	330	0.15	○ - - - - -	○ ○ - - -
531.34	330	0.17	○ - - - - -	○ ○ - - -
463.77	330	0.19	○ - - - - -	○ ○ - - -
406.20	325	0.21	○ - - - - -	○ ○ - - -
362.38	325	0.23	○ - - - - -	○ ○ - - -
325.05	325	0.25	○ - - - - -	○ ○ - - -
295.42	320	0.27	○ ○ - - -	○ ○ - - -
260.46	320	0.30	○ ○ - - -	○ ○ - - -
230.68	315	0.34	○ ○ - - -	○ ○ - - -
206.44	315	0.37	○ ○ - - -	○ ○ - - -
179.67	310	0.41	○ ○ ○ - - -	○ ○ - - -

S22

207.20	315	0.37	○ - - - - -	○ - - - -
177.88	310	0.41	○ - - - - -	○ - - - -
154.74	305	0.46	○ ○ ○ - - -	○ ○ - - -
136.00	300	0.50	○ ○ ○ - - -	○ ○ - - -
120.52	295	0.54	○ ○ ○ - - -	○ ○ ○ - -
107.52	295	0.59	○ ○ ○ - - -	○ ○ ○ - -
96.44	290	0.64	○ ○ ○ - - -	○ ○ ○ - -
87.65	285	0.69	○ ○ ○ ○ - - -	○ ○ ○ - -
77.28	275	0.75	○ ○ ○ ○ - - -	○ ○ ○ - -
71.53	305	0.81	○ - - - - -	○ - - - -
68.44	270	0.82	○ ○ ○ ○ - - -	○ ○ ○ - -
61.41	295	0.91	○ - - - - -	○ - - - -
61.25	265	0.88	- - - ○ - - -	- ○ ○ - -
53.42	290	1.01	○ ○ ○ ○ - - -	○ ○ ○ - -
53.31	255	0.97	- - - ○ - - -	- ○ ○ - -
46.95	285	1.11	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
41.61	280	1.20	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
37.12	275	1.31	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
33.30	265	1.42	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
30.26	260	1.51	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
26.68	250	1.65	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
26.64	295	1.85	○ - - - - -	○ - - - -
23.63	245	1.79	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
22.87	290	2.10	○ - - - - -	○ - - - -
21.15	235	1.93	- - - ○ - - -	- ○ ○ - -
19.89	285	2.34	○ ○ ○ ○ - - -	○ ○ ○ - -
18.40	225	2.12	- - - ○ - - -	- ○ ○ - -
17.49	280	2.59	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
15.50	270	2.83	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
13.82	265	3.00	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
12.40	260	3.00	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
11.27	255	3.00	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
9.94	245	3.00	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
8.80	235	3.00	○ ○ ○ ○ ○ - - -	○ ○ ○ - -
7.88	230	3.00	- - - ○ - - -	- ○ ○ - -
6.85	220	3.00	- - - ○ - - -	- ○ ○ - -

i	T2max [Nm]	P1max [kW]	TA31 TA32 TA33 TA41 TA42 TA43 TA51 TA52 TA53 TA61 TA62 TA63	-W1 -W2 -W3 -W4 -W5
---	---------------	---------------	--	---------------------------------

S32G13

18745	665	<0.05	○ - - - - -	○ - - - -
15891	665	<0.05	○ - - - - -	○ - - - -
13638	665	<0.05	○ - - - - -	○ ○ - - -
11814	665	<0.05	○ - - - - -	○ ○ - - -
10307	665	<0.05	○ - - - - -	○ ○ - - -
9041.7	665	<0.05	○ - - - - -	○ ○ - - -
7963.6	665	<0.05	○ - - - - -	○ ○ - - -
7002.7	665	<0.05	○ - - - - -	○ ○ - - -
6009.8	665	<0.05	○ - - - - -	○ ○ - - -
5206.1	665	<0.05	○ - - - - -	○ ○ - - -
4542.1	660	<0.05	○ - - - - -	○ ○ - - -

S32G12

4043.0	660	<0.05	○ - - - - -	○ - - - -
3454.1	660	0.06	○ - - - - -	○ - - - -
2989.2	660	0.07	○ - - - - -	○ ○ - - -
2612.8	660	0.08	○ - - - - -	○ ○ - - -
2301.9	660	0.09	○ - - - - -	○ ○ - - -
2040.8	660	0.10	○ - - - - -	○ ○ - - -
1818.3	655	0.11	○ - - - - -	○ ○ - - -
1632.3	655	0.12	○ - - - - -	○ ○ - - -
1424.7	655	0.13	○ - - - - -	○ ○ - - -
1247.9	655	0.15	○ - - - - -	○ ○ - - -
1146.9	650	0.16	○ - - - - -	○ ○ - - -
1010.5	650	0.18	○ - - - - -	○ ○ - - -
895.82	650	0.20	○ - - - - -	○ ○ - - -
798.16	645	0.22	○ - - - - -	○ ○ - - -
716.51	645	0.25	○ - - - - -	○ ○ - - -
625.38	640	0.28	○ - - - - -	○ ○ - - -
547.76	635	0.31	○ ○ - - -	○ ○ - - -
492.61	635	0.33	○ ○ - - -	○ ○ - - -
445.64	630	0.36	○ ○ - - -	○ ○ - - -
406.20	625	0.39	○ ○ ○ - - -	○ ○ - - -
362.38	625	0.42	○ ○ ○ - - -	○ ○ - - -
325.05	620	0.47	○ ○ ○ - - -	○ ○ - - -
294.91	615	0.51	○ ○ ○ - - -	○ ○ - - -
261.33	610	0.56	○ ○ ○ - - -	○ ○ - - -
230.03	600	0.62	○ ○ ○ - - -	○ ○ - - -

i	T2max [Nm]	P1max [kW]	TA31 TA32 TA33 TA41 TA42 TA43 TA51 TA52 TA53 TA61 TA62 TA63	W1 W2 W3 W4 W5
---	---------------	---------------	--	----------------------------

S32

271.60	610	0.54	○ - - - - -	○ - - - -
234.71	605	0.61	○ - - - - -	○ - - - -
205.58	595	0.68	○ ○ - - - -	○ ○ - - -
182.00	585	0.74	○ ○ ○ - - -	○ ○ - - -
162.52	580	0.80	○ ○ ○ - - -	○ ○ - - -
146.16	570	0.86	○ ○ ○ - - -	○ ○ - - -
132.22	560	0.92	○ ○ ○ ○ - - -	○ ○ ○ - - -
120.52	550	0.98	○ ○ ○ ○ ○ - - -	○ ○ ○ ○ - - -
107.52	540	1.06	○ ○ ○ ○ ○ - - -	○ ○ ○ ○ - - -
96.44	530	1.14	○ ○ ○ ○ ○ ○ - - -	○ ○ ○ ○ - - -
87.50	515	1.22	- - - - ○ ○ - - -	- ○ ○ - - -
77.54	500	1.32	- - - - ○ ○ - - -	- ○ ○ - - -
68.25	485	1.43	- - - - ○ ○ - - -	- ○ ○ - - -
59.77	465	1.55	- - - - ○ ○ - - -	- ○ ○ - - -
52.50	450	1.69	- - - - ○ - - -	- - ○ ○ - - -
52.21	635	2.12	○ ○ ○ ○ - - -	○ ○ - - -
46.22	625	2.33	○ ○ ○ ○ ○ ○ - - -	○ ○ - - -
41.28	615	2.54	○ ○ ○ ○ ○ ○ - - -	○ ○ - - -
37.12	600	2.75	○ ○ ○ ○ ○ ○ - - -	○ ○ - - -
33.58	590	2.95	○ ○ ○ ○ ○ ○ - - -	○ ○ - - -
30.61	575	3.14	○ ○ ○ ○ ○ ○ - - -	○ ○ - - -
27.31	560	3.42	○ ○ ○ ○ ○ ○ - - -	○ ○ ○ - - -
24.49	545	3.70	○ ○ ○ ○ ○ ○ - - -	○ ○ ○ - - -
22.44	530	3.84	○ ○ ○ ○ ○ ○ - - -	○ ○ ○ - - -
22.22	535	3.96	- - - - ○ ○ - - -	- ○ ○ - - -
20.18	525	4.00	○ ○ ○ ○ ○ ○ - - -	○ ○ ○ - - -
19.69	515	4.00	- - - - ○ ○ - - -	- ○ ○ - - -
18.26	515	4.00	○ ○ ○ ○ ○ ○ - - -	○ ○ ○ - - -
17.33	495	4.00	- - - - ○ ○ - - -	- ○ ○ - - -
16.64	525	4.00	○ ○ ○ ○ ○ ○ - - -	○ ○ ○ - - -
15.18	470	4.00	- - - - ○ ○ - - -	- ○ ○ - - -
14.85	510	4.00	○ ○ ○ ○ ○ ○ - - -	○ ○ ○ - - -
13.33	450	4.00	- - - - ○ - - -	- - ○ ○ - - -
13.32	495	4.00	○ ○ ○ ○ ○ ○ - - -	○ ○ ○ ○ - - -
12.08	485	4.00	- - - - ○ ○ - - -	- ○ ○ - - -
10.71	465	4.00	- - - - ○ ○ - - -	- ○ ○ - - -
9.43	445	4.00	- - - - ○ ○ - - -	- ○ ○ - - -
8.25	425	4.00	- - - - ○ ○ - - -	- ○ ○ - - -
7.25	405	4.00	- - - - ○ - - -	- - ○ ○ - - -

S42G23

20360	1530	<0.05	○ - - - - -	○ - - - -
17395	1530	<0.05	○ - - - - -	○ - - - -
15053	1530	<0.05	○ - - - - -	○ ○ - - -
13158	1530	<0.0	○ - - - - -	○ ○ - - -
11592	1530	<0.05	○ - - - - -	○ ○ ○ - -
10277	1530	<0.05	○ - - - - -	○ ○ ○ - -
9221.9	1530	0.05	○ - - - - -	○ ○ - - -
8060.8	1530	0.06	○ - - - - -	○ ○ - - -
7101.6	1530	0.07	○ - - - - -	○ ○ ○ - -
6295.9	1530	0.08	○ - - - - -	○ ○ ○ - -
5512.1	1530	0.09	○ - - - - -	○ ○ ○ - -
4856.2	1520	0.10	○ - - - - -	○ ○ ○ - -
4305.3	1520	0.11	○ - - - - -	○ ○ ○ - -

i	T2max [Nm]	P1max [kW]	TA31 TA32 TA33 TA41 TA42 TA43 TA51 TA52 TA53 TA61 TA62 TA63	W1 W2 W3 W4 W5
---	---------------	---------------	--	----------------------------

S42G22

3878.1	1520	0.12	○ - - - - -	○ - - - -
3329.4	1520	0.14	○ - - - - -	○ - - - -
2896.2	1520	0.16	○ - - - - -	○ ○ - - -
2545.5	1510	0.18	○ - - - - -	○ ○ - - -
2255.8	1510	0.20	○ - - - - -	○ ○ ○ - -
2012.4	1510	0.22	○ - - - - -	○ ○ ○ - -
1805.1	1510	0.24	○ - - - - -	○ ○ ○ - -
1640.6	1500	0.27	○ - - - - -	○ ○ ○ - -
1446.4	1500	0.30	○ - - - - -	○ ○ ○ - -
1281.1	1500	0.33	○ ○ - - - -	○ ○ ○ - -
1156.1	1490	0.37	○ ○ - - - -	○ ○ ○ - -
1064.2	1490	0.39	○ ○ - - - -	○ ○ ○ - -
934.35	1480	0.44	○ ○ ○ - - -	○ ○ ○ - -
838.10	1470	0.48	○ ○ ○ - - -	○ ○ ○ - -
761.70	1470	0.52	○ ○ ○ - - -	○ ○ ○ - -
671.56	1460	0.58	○ ○ ○ - - -	○ ○ ○ - -
594.78	1450	0.64	○ ○ ○ - - -	○ ○ ○ - -
536.78	1440	0.69	○ ○ ○ - - -	○ ○ ○ - -
494.08	1430	0.73	○ ○ ○ - - -	○ ○ ○ - -
441.60	1420	0.79	○ ○ ○ - - -	○ ○ ○ - -
392.13	1410	0.86	○ ○ ○ - - -	○ ○ ○ - -
384.81	1410	0.88	- - - - - - -	- ○ ○ - - -
347.49	1390	0.96	○ ○ ○ ○ - - -	○ ○ ○ - - -
343.94	1390	0.96	- - - ○ - - -	- ○ ○ - - -
309.22	1380	1.05	○ ○ ○ ○ - - -	○ ○ ○ - - -
305.41	1380	1.06	- - - ○ - - -	- ○ ○ - - -
270.64	1360	1.17	- - - ○ ○ - - -	- ○ ○ - - -
264.91	1360	1.19	○ ○ ○ ○ ○ - - -	○ ○ ○ - - -
240.84	1350	1.29	- - - ○ ○ - - -	- ○ ○ - - -

i	T2max [Nm]	P1max [kW]	TA31 TA32 TA33 TA41 TA42 TA43 TA51 TA52 TA53 TA61 TA62 TA63	-W1 -W2 -W3 -W4 -W5
---	---------------	---------------	--	---------------------------------

S42

247.58	1350	1.26	-- - - o - - - - -	o o - - -
220.00	1330	1.38	-- - - o o o - - - -	o o - - -
197.22	1310	1.49	-- - - o o o o - - -	o o o - -
178.08	1290	1.60	-- - - o o o o o - -	o o o - -
161.78	1270	1.71	-- - - o o o o o - -	o o o - -
147.91	1250	1.81	-- - - o o o o o - -	o o o - -
132.72	1220	1.93	-- - - o o o o o - -	o o o o -
119.78	1180	2.05	-- - - o o o o o o - -	o o o o -
110.25	1160	2.16	-- - - o o o o o o - -	- o o o -
98.54	1130	2.33	-- - - o o o o o o - -	- o o o -
87.50	1090	2.51	-- - - o o o o o o - -	- o o o -
77.54	1050	2.68	-- - - o o o o o o - -	- o o o -
69.00	1000	2.84	-- - - - o o o - - -	- - o o -
59.37	1260	3.59	-- - - o o o - - - -	o o - - -
59.11	920	3.00	-- - - - - - - - - -	- - - o -
53.22	1390	4.38	-- - - o o o o - - - -	o o o - -
52.14	915	3.37	-- - - - - - - - - -	- - - o -
48.05	1360	4.74	-- - - o o o o o o - -	o o o - -
43.65	1320	5.0	-- - - o o o o o o - -	o o o - -
39.91	1250	5.2	-- - - o o o o o o - -	o o o - -
35.81	1250	5.7	-- - - o o o o o o - -	o o o o -
32.48	870	4.32	-- - - o o o o - - - -	o o - - -
32.32	1200	6.1	-- - - o o o o o o - -	o o o o -
29.75	1140	6.2	-- - - o o o o o o - -	- o o o -
29.11	865	4.78	-- - - o o o o o o - -	o o o - -
26.59	1140	7.0	-- - - o o o o o o - -	- o o o -
26.29	855	5.2	-- - - o o o o o o - -	o o o - -
23.88	850	5.7	-- - - o o o o o o - -	o o o - -
23.61	1080	7.4	-- - - o o o o o o - -	- o o o -
21.83	1010	7.3	-- - - o o o o o o - -	o o o - -
20.92	1010	7.5	-- - - o o o o o o - -	- o o o -
19.59	995	7.5	-- - - o o o o o o - -	o o o o -
18.62	950	7.5	-- - - - o o o - - - -	- - o o -
17.68	985	7.5	-- - - o o o o o o - -	o o o o -
16.28	1050	7.5	-- - - - o o o o o o - -	- o o o -
15.95	885	7.5	-- - - - - - - - - -	- - - o -
14.55	1000	7.5	-- - - - o o o o o o - -	- o o o -
14.07	820	7.5	-- - - - - - - - - -	- - - o -
12.92	940	7.5	-- - - - o o o o o o - -	- o o o -
11.45	885	7.5	-- - - - o o o o o o - -	- o o o -
10.19	835	7.5	-- - - - - o o o o - -	- - o o -
8.73	775	7.5	-- - - - - - - - - -	- - - o -
7.70	725	7.5	-- - - - - - - - - -	- - - o -

S02

i	is	n1=3400 1/min				n1=2800 1/min				n1=1700 1/min				n1=1400 1/min			
		n2 [1/min]	T2max [Nm]	P1max [kW]													
189.00	1/63	18	52	0.18	0.55	15	54	0.16	0.53	9.0	57	0.11	0.49	7.4	58	0.10	0.47
159.35	1/63	21	50	0.20	0.57	18	52	0.17	0.55	11	57	0.13	0.50	8.8	58	0.11	0.49
135.95	1/63	25	48	0.22	0.58	21	51	0.19	0.56	13	56	0.14	0.51	10	57	0.12	0.50
117.00	1/63	29	46	0.24	0.59	24	49	0.21	0.58	15	54	0.16	0.53	12	56	0.14	0.51
101.35	1/63	34	44	0.26	0.60	28	47	0.23	0.59	17	53	0.17	0.54	14	55	0.15	0.52
88.20	1/63	39	42	0.28	0.61	32	45	0.25	0.60	19	51	0.19	0.56	16	53	0.16	0.54
77.00	1/63	44	40	0.30	0.62	36	43	0.27	0.61	22	50	0.20	0.57	18	52	0.18	0.55
69.00	1/23	49	58	0.40	0.75	41	61	0.35	0.73	25	67	0.25	0.70	20	69	0.21	0.68
58.18	1/23	58	56	0.45	0.76	48	59	0.40	0.75	29	65	0.28	0.71	24	67	0.24	0.70
49.63	1/23	69	53	0.49	0.77	56	56	0.44	0.76	34	63	0.31	0.72	28	66	0.27	0.71
42.71	1/23	80	51	0.54	0.78	66	54	0.48	0.77	40	61	0.35	0.73	33	64	0.30	0.72
37.00	1/23	92	48	0.58	0.79	76	52	0.52	0.78	46	59	0.38	0.74	38	62	0.34	0.73
32.20	1/23	106	46	0.63	0.79	87	49	0.56	0.79	53	57	0.42	0.75	43	60	0.37	0.74
28.11	1/23	121	43	0.68	0.80	100	47	0.61	0.79	60	55	0.46	0.76	50	58	0.41	0.75
25.00	3/25	136	51	0.75	0.87	112	54	0.73	0.87	68	61	0.51	0.85	56	63	0.44	0.83
21.08	3/25	161	49	0.75	0.88	133	52	0.75	0.87	81	59	0.58	0.85	66	61	0.50	0.84
17.98	3/25	189	46	0.75	0.88	156	49	0.75	0.88	95	56	0.65	0.86	78	59	0.56	0.85
15.48	3/25	220	44	0.75	0.89	181	47	0.75	0.88	110	54	0.72	0.87	90	57	0.63	0.86
13.41	3/25	254	41	0.75	0.89	209	45	0.75	0.88	127	52	0.75	0.87	104	55	0.70	0.86
12.50	6/25	272	55	0.75	0.92	224	58	0.75	0.92	136	65	0.75	0.91	112	67	0.75	0.90
11.67	3/25	291	39	0.75	0.89	240	42	0.75	0.89	146	50	0.75	0.87	120	53	0.75	0.87
10.54	6/25	323	52	0.75	0.93	266	56	0.75	0.92	161	63	0.75	0.91	133	65	0.75	0.90
10.19	3/25	334	37	0.75	0.90	275	40	0.75	0.89	167	48	0.75	0.88	137	51	0.75	0.87
8.99	6/25	378	49	0.75	0.93	311	53	0.75	0.93	189	60	0.75	0.92	156	63	0.75	0.91
7.74	6/25	439	47	0.75	0.94	362	50	0.75	0.93	220	58	0.75	0.92	181	61	0.75	0.92
6.70	6/25	507	44	0.75	0.94	418	48	0.75	0.93	254	56	0.75	0.92	209	59	0.75	0.92
5.83	6/25	583	42	0.75	0.94	480	45	0.75	0.94	291	54	0.75	0.92	240	57	0.75	0.92
5.09	6/25	668	39	0.75	0.94	550	43	0.75	0.94	334	52	0.75	0.93	275	55	0.75	0.92

S02

i	is	n1=900 1/min			n1=700 1/min			n1=500 1/min			n1=10 1/min		
		n2 [1/min]	T2max [Nm]	P1max [kW]									
189.00	1/63	4.8	61	0.07	0.43	3.7	62	0.06	0.41	2.6	63	<0.05	0.39
159.35	1/63	5.6	60	0.08	0.44	4.4	61	0.07	0.42	3.1	62	0.05	0.40
135.95	1/63	6.6	59	0.09	0.46	5.1	61	0.08	0.43	3.7	62	0.06	0.41
117.00	1/63	7.7	58	0.10	0.48	6.0	60	0.08	0.45	4.3	61	0.07	0.42
101.35	1/63	8.9	58	0.11	0.49	6.9	59	0.09	0.46	4.9	61	0.07	0.43
88.20	1/63	10	57	0.12	0.50	7.9	58	0.10	0.48	5.7	60	0.08	0.44
77.00	1/63	12	56	0.14	0.51	9.1	57	0.11	0.49	6.5	59	0.09	0.46
69.00	1/23	13	72	0.15	0.64	10	73	0.13	0.62	7.2	75	0.09	0.60
58.18	1/23	15	71	0.18	0.65	12	72	0.14	0.63	8.6	74	0.11	0.61
49.63	1/23	18	70	0.20	0.67	14	72	0.16	0.64	10	73	0.12	0.62
42.71	1/23	21	68	0.22	0.69	16	70	0.18	0.66	12	73	0.14	0.63
37.00	1/23	24	67	0.24	0.70	19	69	0.20	0.67	14	72	0.16	0.64
32.20	1/23	28	66	0.27	0.71	22	68	0.22	0.69	16	71	0.18	0.65
28.11	1/23	32	64	0.30	0.72	25	67	0.25	0.70	18	70	0.20	0.67
25.00	3/25	36	66	0.31	0.80	28	67	0.25	0.79	20	69	0.19	0.77
21.08	3/25	43	65	0.36	0.81	33	66	0.29	0.80	24	68	0.22	0.78
17.98	3/25	50	64	0.41	0.82	39	66	0.33	0.80	28	67	0.25	0.79
15.48	3/25	58	62	0.45	0.84	45	64	0.37	0.82	32	67	0.28	0.79
13.41	3/25	67	61	0.51	0.84	52	63	0.42	0.83	37	66	0.32	0.80
12.50	6/25	72	71	0.61	0.88	56	72	0.49	0.87	40	74	0.36	0.86
11.67	3/25	77	59	0.56	0.85	60	62	0.46	0.84	43	65	0.36	0.81
10.54	6/25	85	69	0.70	0.88	66	71	0.57	0.87	47	73	0.42	0.87
10.19	3/25	88	57	0.62	0.86	69	61	0.52	0.85	49	64	0.40	0.82
8.99	6/25	100	68	0.75	0.89	78	70	0.65	0.88	56	72	0.48	0.87
7.74	6/25	116	66	0.75	0.90	90	69	0.74	0.89	65	71	0.55	0.87
6.70	6/25	134	65	0.75	0.90	104	67	0.75	0.89	75	70	0.63	0.88
5.83	6/25	154	63	0.75	0.91	120	66	0.75	0.90	86	69	0.70	0.88
5.09	6/25	177	61	0.75	0.92	137	65	0.75	0.91	98	68	0.75	0.89

S12

i	is	n1=3400 1/min			n1=2800 1/min			n1=1700 1/min			n1=1400 1/min				
		n2 [1/min]	T2max [Nm]	P1max [kW]											
168.00	1/40	20	151	0.49	0.66	17	156	0.43	0.64	10	168	0.30	0.59		
143.53	1/40	24	146	0.54	0.67	20	152	0.47	0.65	12	164	0.33	0.61		
124.21	1/40	27	141	0.59	0.68	23	148	0.52	0.67	14	161	0.37	0.63		
108.57	1/40	31	136	0.65	0.69	26	143	0.57	0.68	16	158	0.41	0.64		
95.65	1/40	36	131	0.70	0.70	29	139	0.62	0.69	18	155	0.45	0.65		
84.80	1/40	40	126	0.75	0.70	33	134	0.67	0.69	20	151	0.48	0.66		
75.56	1/40	45	121	0.80	0.71	37	129	0.71	0.70	23	148	0.52	0.67		
67.83	1/40	50	116	0.84	0.72	41	124	0.76	0.71	25	144	0.56	0.68		
60.90	2/29	56	144	1.02	0.82	46	150	0.89	0.81	28	162	0.61	0.78		
59.20	1/40	57	110	0.91	0.73	47	119	0.82	0.72	29	139	0.61	0.69		
52.03	2/29	65	138	1.14	0.83	54	145	0.99	0.82	33	158	0.68	0.79		
51.85	1/40	66	104	0.98	0.73	54	113	0.88	0.72	33	134	0.66	0.69		
45.03	2/29	76	133	1.26	0.83	62	140	1.10	0.83	38	155	0.76	0.80		
39.36	2/29	86	128	1.38	0.84	71	135	1.21	0.83	43	151	0.85	0.81		
34.67	2/29	98	123	1.49	0.85	81	131	1.32	0.84	49	148	0.93	0.82		
30.74	2/29	111	117	1.50	0.85	91	126	1.42	0.84	55	144	1.01	0.82		
27.39	2/29	124	112	1.50	0.86	102	121	1.50	0.85	62	140	1.10	0.83		
24.59	2/29	138	107	1.50	0.86	114	116	1.50	0.85	69	136	1.19	0.83		
22.68	5/27	150	130	1.50	0.91	123	136	1.50	0.91	75	148	1.31	0.89		
21.46	2/29	158	101	1.50	0.86	130	110	1.50	0.86	79	131	1.30	0.84		
19.38	5/27	175	124	1.50	0.92	145	131	1.50	0.91	88	144	1.48	0.90		
18.80	2/29	181	95	1.50	0.87	149	104	1.50	0.86	90	126	1.42	0.84		
16.77	5/27	203	119	1.50	0.92	167	126	1.50	0.92	101	141	1.50	0.90		
14.66	5/27	232	114	1.50	0.93	191	121	1.50	0.92	116	137	1.50	0.91		
12.91	5/27	263	109	1.50	0.93	217	117	1.50	0.92	132	134	1.50	0.91		
11.45	5/27	297	105	1.50	0.93	245	112	1.50	0.93	148	130	1.50	0.91		
10.20	5/27	333	100	1.50	0.93	275	108	1.50	0.93	167	126	1.50	0.92		
9.16	5/27	371	95	1.50	0.93	306	103	1.50	0.93	186	122	1.50	0.92		
7.99	5/27	425	90	1.50	0.93	350	98	1.50	0.93	213	118	1.50	0.92		
7.00	5/27	486	84	1.50	0.94	400	92	1.50	0.93	243	113	1.50	0.93		
												200	120	1.50	0.92

S12

i	is	n1=900 1/min			n1=700 1/min			n1=500 1/min			n1=10 1/min		
		n2 [1/min]	T2max [Nm]	P1max [kW]									
168.00	1/40	5.4	177	0.18	0.54	4.2	179	0.15	0.52	3.0	182	0.11	0.50
143.53	1/40	6.3	175	0.21	0.55	4.9	178	0.17	0.53	3.5	181	0.13	0.51
124.21	1/40	7.2	173	0.23	0.56	5.6	176	0.19	0.54	4.0	179	0.14	0.52
108.57	1/40	8.3	171	0.26	0.57	6.4	175	0.21	0.55	4.6	178	0.16	0.53
95.65	1/40	9.4	169	0.28	0.58	7.3	173	0.24	0.56	5.2	177	0.18	0.54
84.80	1/40	11	167	0.31	0.60	8.3	171	0.26	0.57	5.9	176	0.20	0.54
75.56	1/40	12	164	0.33	0.61	9.3	169	0.28	0.58	6.6	174	0.22	0.55
67.83	1/40	13	162	0.36	0.62	10	167	0.30	0.60	7.4	173	0.24	0.56
60.90	2/29	15	173	0.36	0.73	11	175	0.29	0.72	8.2	178	0.22	0.70
59.20	1/40	15	159	0.40	0.63	12	164	0.33	0.61	8.4	171	0.26	0.57
52.03	2/29	17	171	0.42	0.74	13	174	0.33	0.73	9.6	177	0.25	0.71
51.85	1/40	17	155	0.44	0.64	14	161	0.37	0.62	9.6	169	0.29	0.59
45.03	2/29	20	168	0.47	0.75	16	172	0.38	0.74	11	175	0.28	0.72
39.36	2/29	23	166	0.52	0.76	18	170	0.43	0.74	13	174	0.32	0.73
34.67	2/29	26	164	0.58	0.77	20	168	0.47	0.75	14	173	0.36	0.73
30.74	2/29	29	161	0.63	0.78	23	166	0.52	0.76	16	171	0.39	0.74
27.39	2/29	33	158	0.69	0.79	26	164	0.57	0.77	18	170	0.43	0.75
24.59	2/29	37	156	0.74	0.80	28	162	0.62	0.78	20	168	0.48	0.75
22.68	5/27	40	159	0.77	0.86	31	161	0.61	0.85	22	164	0.45	0.84
21.46	2/29	42	152	0.83	0.81	33	158	0.68	0.79	23	166	0.53	0.76
19.38	5/27	46	157	0.88	0.86	36	160	0.70	0.86	26	163	0.52	0.85
18.80	2/29	48	148	0.91	0.82	37	155	0.75	0.80	27	163	0.59	0.77
16.77	5/27	54	154	1.00	0.87	42	158	0.80	0.86	30	161	0.59	0.85
14.66	5/27	61	152	1.12	0.88	48	156	0.90	0.87	34	160	0.67	0.85
12.91	5/27	70	150	1.24	0.88	54	154	1.01	0.87	39	159	0.75	0.86
11.45	5/27	79	147	1.36	0.89	61	152	1.11	0.88	44	157	0.83	0.86
10.20	5/27	88	144	1.49	0.90	69	150	1.22	0.88	49	156	0.92	0.87
9.16	5/27	98	142	1.50	0.90	76	148	1.33	0.89	55	154	1.01	0.87
7.99	5/27	113	138	1.50	0.90	88	144	1.48	0.90	63	152	1.13	0.88
7.00	5/27	129	134	1.50	0.91	100	141	1.50	0.90	71	149	1.26	0.88

S22

i	is	n1=3400 1/min			n1=2800 1/min			n1=1700 1/min			n1=1400 1/min		
		n2 [1/min]	T2max [Nm]	P1max [kW]									
207.20	1/42	16	280	0.70	0.69	14	290	0.61	0.68	8.2	310	0.42	0.63
177.88	1/42	19	275	0.78	0.70	16	285	0.68	0.69	9.6	305	0.47	0.64
154.74	1/42	22	265	0.86	0.71	18	275	0.75	0.70	11	300	0.52	0.66
136.00	1/42	25	260	0.94	0.72	21	270	0.82	0.71	13	295	0.57	0.67
120.52	1/42	28	250	1.02	0.73	23	265	0.89	0.72	14	290	0.63	0.68
107.52	1/42	32	245	1.09	0.74	26	255	0.96	0.73	16	285	0.68	0.69
96.44	1/42	35	235	1.16	0.75	29	250	1.04	0.73	18	280	0.74	0.70
87.65	1/42	39	230	1.23	0.75	32	245	1.10	0.74	19	275	0.79	0.71
77.28	1/42	44	220	1.33	0.76	36	235	1.18	0.75	22	265	0.86	0.71
71.53	2/29	48	260	1.54	0.84	39	270	1.34	0.83	24	295	0.94	0.78
68.44	1/42	50	210	1.43	0.76	41	225	1.27	0.75	25	260	0.93	0.72
61.41	2/29	55	250	1.71	0.84	46	260	1.50	0.83	28	290	1.05	0.80
61.25	1/42	56	200	1.52	0.77	46	215	1.36	0.76	28	255	1.01	0.73
53.42	2/29	64	240	1.88	0.85	52	250	1.65	0.84	32	280	1.16	0.81
53.31	1/42	64	190	1.64	0.77	53	205	1.48	0.76	32	245	1.10	0.74
46.95	2/29	72	230	2.05	0.85	60	245	1.80	0.84	36	275	1.27	0.82
41.61	2/29	82	220	2.22	0.85	67	235	1.95	0.85	41	270	1.39	0.83
37.12	2/29	92	215	2.38	0.86	75	225	2.11	0.85	46	260	1.50	0.83
33.30	2/29	102	205	2.53	0.86	84	220	2.26	0.85	51	255	1.62	0.84
30.26	2/29	112	196	2.67	0.86	93	210	2.40	0.86	56	250	1.73	0.84
26.68	2/29	127	185	2.84	0.87	105	200	2.57	0.86	64	240	1.88	0.85
26.64	5/27	128	250	3.00	0.92	105	265	3.00	0.91	64	290	2.17	0.89
23.63	2/29	144	174	3.00	0.87	118	191	2.74	0.86	72	230	2.04	0.85
22.87	5/27	149	240	3.00	0.92	122	255	3.00	0.92	74	280	2.45	0.90
21.15	2/29	161	166	3.00	0.87	132	181	2.89	0.87	80	225	2.20	0.85
19.89	5/27	171	230	3.00	0.93	141	245	3.00	0.92	85	275	2.72	0.91
18.40	2/29	185	154	3.00	0.88	152	170	3.00	0.87	92	210	2.39	0.86
17.49	5/27	194	220	3.00	0.93	160	235	3.00	0.92	97	270	2.99	0.91
15.50	5/27	219	215	3.00	0.93	181	225	3.00	0.93	110	260	3.00	0.91
13.82	5/27	246	205	3.00	0.94	203	220	3.00	0.93	123	255	3.00	0.92
12.40	5/27	274	194	3.00	0.94	226	210	3.00	0.93	137	245	3.00	0.92
11.27	5/27	302	187	3.00	0.94	248	205	3.00	0.94	151	240	3.00	0.92
9.94	5/27	342	176	3.0	0.94	282	192	3.0	0.94	171	231	3.0	0.93
8.80	5/27	386	166	3.0	0.94	318	183	3.0	0.94	193	222	3.0	0.93
7.88	5/27	432	158	3.0	0.94	356	173	3.0	0.94	216	214	3.0	0.93
6.85	5/27	496	146	3.0	0.94	409	162	3.0	0.94	248	203	3.0	0.93

S22

i	is	n1=900 1/min			n1=700 1/min			n1=500 1/min			n1=10 1/min		
		n2 [1/min]	T2max [Nm]	P1max [kW]									
207.20	1/42	4.3	325	0.25	0.58	3.4	325	0.20	0.56	2.4	330	0.16	0.54
177.88	1/42	5.1	320	0.29	0.59	3.9	325	0.23	0.57	2.8	330	0.18	0.55
154.74	1/42	5.8	320	0.32	0.60	4.5	325	0.26	0.58	3.2	325	0.20	0.56
136.00	1/42	6.6	315	0.36	0.61	5.1	320	0.29	0.59	3.7	325	0.22	0.57
120.52	1/42	7.5	310	0.40	0.62	5.8	320	0.32	0.60	4.1	325	0.24	0.58
107.52	1/42	8.4	310	0.43	0.63	6.5	315	0.36	0.61	4.7	320	0.27	0.58
96.44	1/42	9.3	305	0.47	0.64	7.3	315	0.39	0.61	5.2	320	0.29	0.59
87.65	1/42	10	300	0.50	0.65	8.0	310	0.42	0.62	5.7	320	0.32	0.60
77.28	1/42	12	295	0.54	0.67	9.1	305	0.46	0.64	6.5	315	0.35	0.60
71.53	2/29	13	315	0.56	0.75	9.8	320	0.45	0.73	7.0	325	0.34	0.71
68.44	1/42	13	290	0.59	0.68	10	300	0.50	0.65	7.3	315	0.39	0.61
61.41	2/29	15	310	0.63	0.75	11	315	0.51	0.74	8.1	325	0.38	0.72
61.25	1/42	15	290	0.65	0.68	11	300	0.54	0.66	8.2	310	0.42	0.63
53.42	2/29	17	310	0.71	0.76	13	315	0.58	0.75	9.4	320	0.43	0.73
53.31	1/42	17	280	0.71	0.70	13	290	0.59	0.68	9.4	305	0.47	0.64
46.95	2/29	19	305	0.79	0.77	15	310	0.64	0.76	11	320	0.48	0.74
41.61	2/29	22	300	0.87	0.78	17	310	0.71	0.76	12	315	0.53	0.75
37.12	2/29	24	295	0.95	0.79	19	305	0.78	0.77	13	315	0.59	0.75
33.30	2/29	27	290	1.03	0.80	21	300	0.85	0.78	15	310	0.65	0.76
30.26	2/29	30	285	1.10	0.80	23	295	0.92	0.78	17	310	0.70	0.76
26.68	2/29	34	280	1.20	0.82	26	290	1.01	0.79	19	305	0.78	0.77
26.64	5/27	34	310	1.25	0.87	26	315	1.00	0.87	19	305	0.71	0.84
23.63	2/29	38	270	1.32	0.82	30	285	1.10	0.80	21	300	0.86	0.78
22.87	5/27	39	305	1.44	0.88	31	305	1.13	0.87	22	300	0.81	0.85
21.15	2/29	43	265	1.43	0.83	33	280	1.19	0.82	24	295	0.93	0.78
19.89	5/27	45	300	1.63	0.88	35	305	1.28	0.87	25	300	0.92	0.86
18.40	2/29	49	255	1.57	0.84	38	270	1.31	0.82	27	290	1.04	0.80
17.49	5/27	51	300	1.82	0.88	40	300	1.43	0.88	29	295	1.02	0.87
15.50	5/27	58	295	2.01	0.89	45	295	1.59	0.88	32	295	1.14	0.87
13.82	5/27	65	290	2.20	0.89	51	290	1.74	0.88	36	285	1.24	0.88
12.40	5/27	73	285	2.40	0.90	56	285	1.90	0.89	40	285	1.36	0.88
11.27	5/27	80	280	2.58	0.90	62	290	2.12	0.89	44	305	1.60	0.88
9.94	5/27	91	270	2.83	0.91	70	285	2.35	0.90	50	300	1.78	0.88
8.80	5/27	102	265	3.00	0.91	80	280	2.58	0.90	57	295	1.97	0.89
7.88	5/27	114	260	3.00	0.91	89	275	2.79	0.91	63	290	2.16	0.89
6.85	5/27	131	250	3.00	0.92	102	265	3.00	0.91	73	285	2.41	0.90

S32

i	is	n1=3400 1/min			n1=2800 1/min			n1=1700 1/min			n1=1400 1/min		
		n2 [1/min]	T2max [Nm]	P1max [kW]									
271.60	1/42	13	545	1.03	0.69	10	565	0.91	0.67	6.3	600	0.63	0.62
234.71	1/42	14	530	1.14	0.70	12	550	0.99	0.69	7.2	590	0.71	0.63
205.58	1/42	17	515	1.25	0.71	14	535	1.09	0.70	8.3	580	0.78	0.65
182.00	1/42	19	500	1.35	0.72	15	520	1.19	0.71	9.3	570	0.85	0.66
162.52	1/42	21	485	1.45	0.73	17	510	1.28	0.72	10	560	0.91	0.67
146.16	1/42	23	470	1.55	0.74	19	495	1.37	0.72	12	550	0.98	0.69
132.22	1/42	26	455	1.65	0.74	21	480	1.46	0.73	13	540	1.05	0.69
120.52	1/42	28	440	1.75	0.75	23	470	1.54	0.74	14	530	1.12	0.70
107.52	1/42	32	425	1.87	0.75	26	455	1.66	0.74	16	520	1.21	0.71
96.44	1/42	35	405	1.98	0.76	29	440	1.78	0.75	18	505	1.30	0.72
87.50	1/42	39	390	2.08	0.77	32	425	1.88	0.75	19	495	1.38	0.73
77.54	1/42	44	375	2.21	0.77	36	400	2.00	0.76	22	475	1.49	0.73
68.25	1/42	50	350	2.35	0.78	41	385	2.14	0.77	25	460	1.62	0.74
59.77	1/42	57	330	2.52	0.78	47	360	2.27	0.78	28	440	1.76	0.75
52.50	1/42	65	310	2.66	0.79	53	340	2.44	0.78	32	420	1.89	0.75
52.21	3/32	65	530	4.00	0.89	54	555	3.53	0.88	33	615	2.47	0.85
46.22	3/32	74	510	4.00	0.89	61	540	3.86	0.89	37	605	2.70	0.86
41.28	3/32	82	490	4.00	0.90	68	520	4.00	0.89	41	590	2.93	0.87
37.12	3/32	92	475	4.00	0.90	75	505	4.00	0.89	46	575	3.14	0.88
33.58	3/32	101	455	4.00	0.90	83	490	4.00	0.90	51	565	3.38	0.88
30.61	3/32	111	440	4.00	0.90	91	475	4.00	0.90	56	550	3.63	0.88
27.31	3/32	125	420	4.00	0.91	103	455	4.00	0.90	62	535	3.93	0.89
24.49	3/32	139	400	4.00	0.91	114	435	4.00	0.90	69	515	4.00	0.89
22.44	5/29	151	445	4.00	0.94	125	470	4.00	0.93	76	535	4.00	0.91
22.22	3/32	153	385	4.00	0.91	126	420	4.00	0.91	77	505	4.00	0.89
20.18	5/29	168	425	4.00	0.94	139	455	4.00	0.93	84	525	4.00	0.92
19.69	3/32	173	360	4.00	0.92	142	395	4.00	0.91	86	485	4.00	0.90
18.26	5/29	186	410	4.00	0.94	153	440	4.00	0.94	93	510	4.00	0.92
17.33	3/32	196	335	4.00	0.92	162	375	4.00	0.91	98	460	4.00	0.90
16.64	5/29	204	395	4.00	0.94	168	425	4.00	0.94	102	500	4.00	0.92
15.18	3/32	224	315	4.00	0.92	184	345	4.00	0.92	112	440	4.00	0.90
14.85	5/29	229	380	4.00	0.94	189	410	4.00	0.94	114	485	4.00	0.93
13.33	3/32	255	290	4.00	0.92	210	325	4.00	0.92	128	415	4.00	0.91
13.32	5/29	255	360	4.00	0.94	210	395	4.00	0.94	128	470	4.00	0.93
12.08	5/29	281	340	4.00	0.94	232	375	4.00	0.94	141	455	4.00	0.93
10.71	5/29	318	320	4.00	0.95	261	355	4.00	0.94	159	435	4.00	0.94
9.43	5/29	361	300	4.00	0.95	297	335	4.00	0.94	180	415	4.00	0.94
8.25	5/29	412	280	4.00	0.95	339	310	4.00	0.95	206	395	4.00	0.94
7.25	5/29	469	260	4.00	0.95	386	290	4.00	0.95	234	375	4.00	0.94

S32

i	is	n1=900 1/min				n1=700 1/min				n1=500 1/min				n1=10 1/min			
		n2 [1/min]	T2max [Nm]	P1max [kW]													
271.60	1/42	3.3	630	0.38	0.58	2.6	635	0.31	0.56	1.8	645	0.23	0.53	0.037	665	<0.05	0.48
234.71	1/42	3.8	625	0.42	0.59	3.0	635	0.35	0.57	2.1	640	0.26	0.54	0.043	665	<0.05	0.48
205.58	1/42	4.4	620	0.47	0.60	3.4	630	0.38	0.58	2.4	640	0.29	0.55	0.049	665	<0.05	0.48
182.00	1/42	4.9	615	0.52	0.61	3.8	625	0.42	0.59	2.7	635	0.32	0.56	0.055	665	<0.05	0.48
162.52	1/42	5.5	610	0.57	0.61	4.3	620	0.47	0.60	3.1	630	0.35	0.57	0.062	665	<0.05	0.48
146.16	1/42	6.2	600	0.62	0.62	4.8	615	0.51	0.60	3.4	630	0.38	0.59	0.068	665	<0.05	0.48
132.22	1/42	6.8	595	0.68	0.63	5.3	610	0.55	0.61	3.8	625	0.42	0.59	0.076	665	<0.05	0.48
120.52	1/42	7.5	590	0.72	0.64	5.8	605	0.60	0.62	4.1	620	0.45	0.60	0.083	665	<0.05	0.48
107.52	1/42	8.4	580	0.79	0.65	6.5	600	0.65	0.63	4.7	615	0.50	0.60	0.093	665	<0.05	0.48
96.44	1/42	9.3	570	0.85	0.66	7.3	590	0.71	0.63	5.2	610	0.54	0.61	0.10	665	<0.05	0.48
87.50	1/42	10	565	0.90	0.67	8.0	585	0.76	0.64	5.7	605	0.59	0.62	0.11	665	<0.05	0.48
77.54	1/42	12	550	0.98	0.69	9.0	575	0.83	0.66	6.4	600	0.65	0.62	0.13	665	<0.05	0.48
68.25	1/42	13	540	1.07	0.70	10	565	0.90	0.67	7.3	590	0.71	0.64	0.15	665	<0.05	0.48
59.77	1/42	15	525	1.17	0.71	12	550	0.98	0.69	8.4	580	0.79	0.65	0.17	665	<0.05	0.48
52.50	1/42	17	510	1.27	0.72	13	535	1.08	0.70	9.5	570	0.86	0.66	0.19	665	<0.05	0.48
52.21	3/32	17	665	1.46	0.83	13	680	1.17	0.82	9.6	695	0.88	0.79	0.19	730	<0.05	0.73
46.22	3/32	19	660	1.62	0.83	15	675	1.30	0.82	11	690	0.98	0.80	0.22	730	<0.05	0.73
41.28	3/32	22	650	1.78	0.83	17	665	1.43	0.83	12	685	1.08	0.81	0.24	730	<0.05	0.73
37.12	3/32	24	645	1.95	0.84	19	660	1.57	0.83	13	680	1.17	0.82	0.27	730	<0.05	0.73
33.58	3/32	27	635	2.12	0.84	21	655	1.72	0.83	15	675	1.28	0.82	0.30	730	<0.05	0.73
30.61	3/32	29	625	2.28	0.85	23	650	1.86	0.84	16	670	1.39	0.82	0.33	730	<0.05	0.73
27.31	3/32	33	615	2.49	0.85	26	640	2.04	0.84	18	665	1.53	0.83	0.37	730	<0.05	0.73
24.49	3/32	37	605	2.70	0.86	29	630	2.23	0.85	20	655	1.69	0.83	0.41	730	<0.05	0.73
22.44	5/29	40	525	2.47	0.89	31	520	1.92	0.88	22	510	1.37	0.87	0.45	475	<0.05	0.81
22.22	3/32	41	590	2.89	0.87	32	620	2.40	0.85	23	650	1.83	0.84	0.45	730	<0.05	0.73
20.18	5/29	45	515	2.68	0.89	35	510	2.09	0.89	25	505	1.49	0.88	0.50	465	<0.05	0.81
19.69	3/32	46	575	3.14	0.88	36	610	2.63	0.86	25	640	2.02	0.84	0.51	730	0.05	0.73
18.26	5/29	49	505	2.92	0.90	38	505	2.27	0.89	27	500	1.62	0.88	0.55	460	<0.05	0.81
17.33	3/32	52	560	3.45	0.88	40	595	2.89	0.87	29	630	2.24	0.85	0.58	730	0.06	0.73
16.64	5/29	54	575	3.62	0.90	42	595	2.94	0.89	30	615	2.19	0.88	0.60	565	<0.05	0.81
15.18	3/32	59	540	3.80	0.89	46	575	3.16	0.88	33	615	2.49	0.85	0.66	730	0.07	0.73
14.85	5/29	61	565	3.97	0.90	47	585	3.24	0.89	34	590	2.35	0.89	0.67	540	<0.05	0.81
13.33	3/32	68	520	4.00	0.89	53	560	3.48	0.88	38	600	2.74	0.86	0.75	730	0.08	0.73
13.32	5/29	68	550	4.00	0.91	53	580	3.54	0.90	38	575	2.55	0.89	0.75	525	0.05	0.81
12.08	5/29	74	540	4.00	0.91	58	570	3.83	0.90	41	595	2.90	0.89	0.83	645	0.07	0.81
10.71	5/29	84	525	4.00	0.92	65	555	4.00	0.91	47	590	3.22	0.89	0.93	625	0.08	0.81
9.43	5/29	95	510	4.00	0.92	74	540	4.00	0.91	53	575	3.57	0.90	1.1	660	0.09	0.81
8.25	5/29	109	490	4.00	0.93	85	525	4.00	0.92	61	565	3.96	0.90	1.2	625	0.10	0.81
7.25	5/29	124	475	4.00	0.93	97	510	4.00	0.92	69	550	4.00	0.91	1.4	595	0.11	0.81

S42

i	is	n1=3400 1/min			n1=2800 1/min			n1=1700 1/min			n1=1400 1/min		
		n2 [1/min]	T2max [Nm]	P1max [kW]									
247.58	1/42	14	1140	2.28	0.72	11	1190	2.01	0.70	6.9	1320	1.46	0.65
220.00	1/42	15	1100	2.46	0.73	13	1160	2.17	0.71	7.7	1290	1.59	0.66
197.22	1/42	17	1070	2.62	0.74	14	1130	2.33	0.72	8.6	1270	1.71	0.67
178.08	1/42	19	1030	2.78	0.74	16	1100	2.48	0.73	9.5	1240	1.82	0.68
161.78	1/42	21	1000	2.94	0.75	17	1070	2.62	0.74	11	1220	1.93	0.69
147.91	1/42	23	970	3.08	0.76	19	1040	2.76	0.74	11	1190	2.03	0.71
132.72	1/42	26	935	3.28	0.76	21	1000	2.95	0.75	13	1160	2.18	0.71
119.78	1/42	28	900	3.48	0.77	23	965	3.11	0.76	14	1130	2.33	0.72
110.25	1/42	31	865	3.62	0.77	25	935	3.26	0.76	15	1110	2.45	0.73
98.54	1/42	35	820	3.81	0.78	28	895	3.48	0.77	17	1070	2.62	0.74
87.50	1/42	39	775	4.03	0.78	32	850	3.69	0.77	19	1030	2.81	0.75
77.54	1/42	44	730	4.25	0.79	36	800	3.88	0.78	22	985	3.01	0.75
69.00	1/42	49	685	4.46	0.79	41	760	4.11	0.78	25	945	3.20	0.76
59.37	3/34	57	1150	7.5	0.91	47	1220	6.7	0.90	29	1260	4.32	0.87
59.11	1/42	58	630	4.79	0.79	47	695	4.37	0.79	29	895	3.50	0.77
53.22	3/34	64	1110	7.5	0.91	53	1180	7.2	0.90	32	1340	5.1	0.88
52.14	1/42	65	585	4.99	0.80	54	655	4.65	0.79	33	845	3.72	0.77
48.05	3/34	71	1070	7.5	0.91	58	1150	7.5	0.91	35	1310	5.5	0.89
43.65	3/34	78	1040	7.5	0.91	64	1110	7.5	0.91	39	1280	5.8	0.89
39.91	3/34	85	1000	7.5	0.91	70	1080	7.5	0.91	43	1250	6.2	0.90
35.81	3/34	95	960	7.5	0.91	78	1040	7.5	0.91	47	1210	6.7	0.90
32.48	5/31	105	895	7.5	0.94	86	890	7.5	0.93	52	875	5.3	0.91
32.32	3/34	105	925	7.5	0.91	87	995	7.5	0.91	53	1180	7.2	0.90
29.75	3/34	114	890	7.5	0.92	94	965	7.5	0.91	57	1140	7.5	0.91
29.11	5/31	117	890	7.5	0.94	96	885	7.5	0.93	58	870	5.8	0.92
26.59	3/34	128	840	7.5	0.92	105	925	7.5	0.91	64	1110	7.5	0.91
26.29	5/31	129	880	7.5	0.94	107	875	7.5	0.94	65	865	6.3	0.92
23.88	5/31	142	875	7.5	0.95	117	870	7.5	0.94	71	855	6.9	0.92
23.61	3/34	144	790	7.5	0.92	119	875	7.5	0.92	72	1070	7.5	0.91
21.83	5/31	156	860	7.5	0.95	128	930	7.5	0.94	78	1010	7.5	0.93
20.92	3/34	163	740	7.5	0.93	134	820	7.5	0.92	81	1010	7.5	0.91
19.59	5/31	174	825	7.5	0.95	143	890	7.5	0.95	87	1000	7.5	0.93
18.62	3/34	183	695	7.5	0.93	150	775	7.5	0.92	91	950	7.5	0.91
17.68	5/31	192	790	7.5	0.95	158	855	7.5	0.95	96	990	7.5	0.93
16.28	5/31	209	760	7.5	0.95	172	825	7.5	0.95	104	995	7.5	0.94
15.95	3/34	213	640	7.5	0.93	176	705	7.5	0.93	107	885	7.5	0.91
14.55	5/31	234	715	7.5	0.95	192	790	7.5	0.95	117	960	7.5	0.94
14.07	3/34	242	590	7.5	0.93	199	665	7.5	0.93	121	820	7.5	0.92
12.92	5/31	263	675	7.5	0.95	217	745	7.5	0.95	132	920	7.5	0.94
11.45	5/31	297	630	7.5	0.95	245	695	7.5	0.95	149	880	7.5	0.95
10.19	5/31	334	585	7.5	0.95	275	655	7.5	0.95	167	835	7.5	0.95
8.73	5/31	390	540	7.5	0.95	321	600	7.5	0.95	195	775	7.5	0.95
7.70	5/31	442	495	7.5	0.96	364	560	7.5	0.95	221	725	7.5	0.95

S42

i	is	n1=900 1/min				n1=700 1/min				n1=500 1/min				n1=10 1/min			
		n2 [1/min]	T2max [Nm]	P1max [kW]													
247.58	1/42	3.6	1410	0.88	0.61	2.8	1430	0.73	0.58	2.0	1460	0.56	0.55	0.040	1530	<0.05	0.48
220.00	1/42	4.1	1390	0.97	0.62	3.2	1420	0.80	0.59	2.3	1450	0.62	0.56	0.045	1530	<0.05	0.48
197.22	1/42	4.6	1380	1.06	0.62	3.5	1410	0.86	0.61	2.5	1440	0.67	0.57	0.051	1530	<0.05	0.48
178.08	1/42	5.1	1370	1.15	0.63	3.9	1400	0.94	0.61	2.8	1430	0.73	0.58	0.056	1530	<0.05	0.48
161.78	1/42	5.6	1350	1.24	0.63	4.3	1390	1.01	0.62	3.1	1420	0.78	0.59	0.062	1530	<0.05	0.48
147.91	1/42	6.1	1340	1.33	0.64	4.7	1380	1.09	0.62	3.4	1410	0.83	0.60	0.068	1530	<0.05	0.48
132.72	1/42	6.8	1320	1.44	0.65	5.3	1360	1.19	0.63	3.8	1400	0.90	0.61	0.075	1530	<0.05	0.48
119.78	1/42	7.5	1300	1.55	0.66	5.8	1340	1.29	0.64	4.2	1390	0.98	0.62	0.083	1530	<0.05	0.48
110.25	1/42	8.2	1280	1.65	0.67	6.3	1330	1.38	0.64	4.5	1380	1.05	0.62	0.091	1530	<0.05	0.48
98.54	1/42	9.1	1250	1.77	0.68	7.1	1310	1.49	0.65	5.1	1370	1.16	0.63	0.10	1530	<0.05	0.48
87.50	1/42	10	1220	1.91	0.69	8.0	1290	1.62	0.66	5.7	1350	1.27	0.64	0.11	1530	<0.05	0.48
77.54	1/42	12	1190	2.04	0.71	9.0	1260	1.76	0.68	6.4	1330	1.39	0.64	0.13	1530	<0.05	0.48
69.00	1/42	13	1000	1.91	0.72	10	1000	1.54	0.69	7.2	1000	1.16	0.65	0.14	1000	<0.05	0.48
59.37	3/34	15	1260	2.34	0.85	12	1260	1.85	0.84	8.4	1260	1.36	0.81	0.17	1260	<0.05	0.76
59.11	1/42	15	920	2.02	0.73	12	920	1.61	0.71	8.5	920	1.22	0.67	0.17	920	<0.05	0.48
53.22	3/34	17	1460	3.03	0.86	13	1470	2.39	0.85	9.4	1430	1.71	0.82	0.19	1320	<0.05	0.76
52.14	1/42	17	1070	2.62	0.74	13	1150	2.25	0.72	9.6	1240	1.83	0.68	0.19	1530	0.06	0.48
48.05	3/34	19	1450	3.31	0.86	15	1460	2.61	0.85	10	1420	1.86	0.83	0.21	1300	<0.05	0.76
43.65	3/34	21	1320	3.31	0.86	16	1320	2.59	0.85	11	1320	1.89	0.84	0.23	1280	<0.05	0.76
39.91	3/34	23	1250	3.41	0.87	18	1250	2.68	0.86	13	1250	1.94	0.84	0.25	1250	<0.05	0.76
35.81	3/34	25	1250	3.78	0.87	20	1250	2.97	0.86	14	1250	2.15	0.85	0.28	1250	<0.05	0.76
32.48	5/31	28	865	2.78	0.90	22	855	2.16	0.89	15	835	1.54	0.87	0.31	795	<0.05	0.83
32.32	3/34	28	1200	4.00	0.87	22	1200	3.15	0.86	15	1200	2.28	0.85	0.31	1200	0.05	0.76
29.75	3/34	30	1140	4.12	0.88	24	1140	3.24	0.87	17	1140	2.34	0.86	0.34	1140	0.05	0.76
29.11	5/31	31	855	3.07	0.90	24	855	2.39	0.90	17	835	1.71	0.88	0.34	790	<0.05	0.83
26.59	3/34	34	1140	4.57	0.88	26	1140	3.61	0.87	19	1140	2.61	0.86	0.38	1140	0.06	0.76
26.29	5/31	34	845	3.36	0.91	27	845	2.61	0.90	19	825	1.86	0.88	0.38	775	<0.05	0.83
23.88	5/31	38	840	3.65	0.91	29	835	2.84	0.90	21	820	2.03	0.89	0.42	765	<0.05	0.83
23.61	3/34	38	1080	4.84	0.89	30	1080	3.82	0.88	21	1080	2.78	0.86	0.42	1080	0.06	0.76
21.83	5/31	41	995	4.71	0.91	32	985	3.67	0.90	23	980	2.62	0.90	0.46	905	0.05	0.83
20.92	3/34	43	1010	5.1	0.90	33	1010	4.01	0.88	24	1010	2.91	0.87	0.48	1010	0.07	0.76
19.59	5/31	46	985	5.2	0.91	36	975	4.03	0.91	26	970	2.88	0.90	0.51	895	0.06	0.83
18.62	3/34	48	950	5.3	0.90	38	950	4.20	0.89	27	950	3.06	0.87	0.54	950	0.07	0.76
17.68	5/31	51	970	5.6	0.91	40	960	4.39	0.91	28	955	3.14	0.90	0.57	880	0.06	0.83
16.28	5/31	55	1180	7.5	0.92	43	1230	6.1	0.91	31	1240	4.42	0.90	0.61	1140	0.09	0.83
15.95	3/34	56	885	5.8	0.91	44	885	4.52	0.90	31	885	3.30	0.88	0.63	885	0.08	0.76
14.55	5/31	62	1000	7.0	0.92	48	1000	5.5	0.91	34	1000	3.98	0.91	0.69	1000	0.09	0.83
14.07	3/34	64	820	6.0	0.91	50	820	4.73	0.90	36	820	3.44	0.89	0.71	820	0.08	0.76
12.92	5/31	70	940	7.4	0.92	54	940	5.8	0.92	39	940	4.20	0.91	0.77	940	0.09	0.83
11.45	5/31	79	885	7.5	0.93	61	885	6.2	0.92	44	885	4.45	0.91	0.87	885	0.10	0.83
10.19	5/31	88	835	7.5	0.93	69	835	6.5	0.92	49	835	4.70	0.91	0.98	835	0.10	0.83
8.73	5/31	103	775	7.5	0.94	80	775	7.0	0.93	57	775	5.1	0.92	1.1	775	0.11	0.83

Helical worm gear units S

Type	n2 [1/min]	T2 [Nm]	cG	i	~kg
------	------------	---------	----	---	-----

0.25 kW

S12A DM71K4	13
S12B DM71K4	13
S12C DM71K4	14
8.4 163 1.05 168.00	
9.8 143 1.15 143.53	
11 128 1.30 124.21	
13 114 1.40 108.57	
15 102 1.55 95.65	
17 92 1.70 84.80	
19 83 1.85 75.56	
21 76 2.00 67.83	
23 79 2.1 60.90	
24 68 2.2 59.20	
27 68 2.4 52.03	
27 60 2.4 51.85	
31 60 2.6 45.03	
36 53 2.9 39.36	
S02A DM71K4	9
S02B DM71K4	9
S02C DM71K4	10
20 80 0.85 69.00	
24 69 1.00 58.18	
28 60 1.10 49.63	
33 52 1.20 42.71	
38 46 1.35 37.00	
44 40 1.50 32.20	
50 36 1.65 28.11	
56 35 1.75 25.00	
67 30 2.0 21.08	
78 26 2.3 17.98	
91 23 2.5 15.48	
105 20 2.8 13.41	
113 19 3.5 12.50	
121 17 3.1 11.67	
134 16 4.0 10.54	
138 15 3.4 10.19	
157 14 4.5 8.99	
182 12 5.0 7.74	
210 10 5.6 6.70	
242 9.1 6.3 5.83	
277 8.0 6.9 5.09	

Type	n2 [1/min]	T2 [Nm]	cG	i	~kg
------	------------	---------	----	---	-----

0.37 kW

S32A DM71G4	30
S32B DM71G4	30
S32C DM71G4	32
5.2 415 1.45 271.60	
6.0 365 1.65 234.71	
6.9 325 1.85 205.58	
7.7 290 2.0 182.00	
8.7 265 2.2 162.52	
9.6 245 2.3 146.16	
11 225 2.5 132.22	
12 210 2.6 120.52	
13 188 2.9 107.52	
S22G12A DM71G4	24
S22G12B DM71G4	24
S22G12C DM71G4	26
5.4 385 0.85 260.46	
6.1 345 0.90 230.68	
6.8 315 1.00 206.44	
7.8 280 1.10 179.67	

Type	n2 [1/min]	T2 [Nm]	cG	i	~kg
------	------------	---------	----	---	-----

0.37 kW

S02A DM71G4	10
S02B DM71G4	10
S02C DM71G4	11
33 77 0.85 42.71	
38 68 0.90 37.00	
44 60 1.00 32.20	
50 53 1.10 28.11	
56 52 1.20 25.00	
67 45 1.35 21.08	
78 38 1.55 17.98	
91 33 1.70 15.48	
105 29 1.90 13.41	
113 28 2.4 12.50	
121 25 2.1 11.67	
134 24 2.7 10.54	
138 22 2.3 10.19	
157 21 3.1 8.99	
182 18 3.4 7.74	
210 15 3.8 6.70	
242 13 4.2 5.83	
277 12 4.7 5.09	

Type	n2 [1/min]	T2 [Nm]	cG	i	~kg
------	------------	---------	----	---	-----

0.55 kW

S22A DM80K4	21
S22B DM80K4	21
S22C DM80K4	23
9.1 370 0.85 154.74	
10 330 0.90 136.00	
12 300 1.00 120.52	
13 270 1.10 107.52	
15 245 1.15 96.44	
16 225 1.25 87.65	
18 205 1.35 77.28	
21 181 1.50 68.44	
26 158 1.85 53.42	
30 141 2.0 46.95	
34 127 2.2 41.61	
38 114 2.4 37.12	
42 103 2.6 33.30	
46 94 2.8 30.26	
53 84 3.0 26.68	

0.55 kW

S42G22A DM80K4	56
S42G22B DM80K4	56
S42G22C DM80K4	59
1.5 1850 0.80 934.35	
1.7 1680 0.90 838.10	
1.8 1550 0.95 761.70	
2.1 1390 1.05 671.56	
2.4 1250 1.15 594.78	
2.6 1150 1.25 536.78	
2.8 1070 1.35 494.08	
3.2 980 1.45 441.60	
3.6 895 1.55 392.13	
4.0 800 1.75 347.49	
4.5 720 1.90 309.22	
5.3 625 2.2 264.91	
S42A DM80K4	50
S42B DM80K4	50
S42C DM80K4	53
5.7 590 2.3 247.58	
6.4 530 2.5 220.00	
7.1 480 2.7 197.22	
7.9 440 2.9 178.08	
S32G12A DM80K4	37
S32G12B DM80K4	37
S32G12C DM80K4	39
4.3 730 0.85 325.05	
4.8 665 0.90 294.91	
5.4 600 1.00 261.33	
6.1 535 1.15 230.03	
S32A DM80K4	32
S32B DM80K4	32
S32C DM80K4	34
6.8 485 1.25 205.58	
7.7 435 1.35 182.00	
8.6 395 1.45 162.52	
9.6 360 1.55 146.16	
11 335 1.70 132.22	
12 310 1.80 120.52	
13 280 1.95 107.52	
15 255 2.1 96.44	

0.75 kW

S42G22A DM80GC4 IE2	57
S42G22B DM80GC4 IE2	57
S42G22C DM80GC4 IE2	61
2.4 1700 0.85 594.78	
2.6 1560 0.90 536.78	
2.9 1460 1.00 494.08	
3.2 1340 1.05 441.60	
3.6 1220 1.15 392.13	
4.1 1090 1.30 347.49	
4.6 975 1.40 309.22	
5.3 850 1.60 264.91	

Helical worm gear units S

Type		~kg
n2 [1/min]	T2 [Nm]	cG i

2.2 kW

S42A DM100LX4 IE2	65
S42B DM100LX4 IE2	65
S42C DM100LX4 IE2	68
8.7 1620 0.80 161.78	
9.5 1500 0.85 147.91	
11 1370 0.90 132.72	
12 1260 0.95 119.78	
13 1170 1.00 110.25	
14 1060 1.05 98.54	
16 955 1.15 87.50	
18 855 1.25 77.54	
20 770 1.30 69.00	
26 690 2.0 53.22	
29 625 2.2 48.05	
32 575 2.3 43.65	
35 525 2.4 39.91	
39 475 2.6 35.81	
44 435 2.8 32.32	
47 400 2.9 29.75	
48 395 2.2 29.11	
53 360 3.2 26.59	
54 360 2.4 26.29	
59 325 2.6 23.88	
S32A DM100LX4 IE2	48
S32B DM100LX4 IE2	48
S32C DM100LX4 IE2	50
34 525 1.15 41.28	
38 480 1.25 37.12	
42 435 1.35 33.58	
46 400 1.45 30.61	
52 360 1.55 27.31	
58 325 1.70 24.49	
63 300 1.75 22.44	
63 295 1.80 22.22	
70 275 1.90 20.18	
72 260 1.95 19.69	
77 250 2.1 18.26	
81 230 2.1 17.33	
85 230 2.3 16.64	
93 205 2.3 15.18	
95 205 2.5 14.85	
106 179 2.5 13.33	
106 183 2.7 13.32	
117 167 2.9 12.08	
S22A DM100LX4 IE2	37
S22B DM100LX4 IE2	37
S22C DM100LX4 IE2	39
60 295 0.80 23.63	
67 265 0.90 21.15	
77 235 0.95 18.40	
91 210 1.30 15.50	
102 188 1.40 13.82	
114 169 1.55 12.40	
125 154 1.65 11.27	
142 136 1.80 9.94	
160 121 1.95 8.80	
179 109 2.1 7.88	
206 95 2.3 6.85	

Type		~kg
n2 [1/min]	T2 [Nm]	cG i

3.0 kW

S42A DM112M4 IE2	71
S42B DM112M4 IE2	71
S42C DM112M4 IE2	75
14 1450 0.80 98.54	
16 1300 0.85 87.50	
18 1170 0.90 77.54	
20 1050 0.95 69.00	
26 940 1.45 53.22	
29 855 1.60 48.05	
32 780 1.70 43.65	
35 720 1.75 39.91	
39 650 1.95 35.81	
44 590 2.0 32.32	
47 545 2.1 29.75	
48 540 1.60 29.11	
53 490 2.3 26.59	
54 490 1.75 26.29	
59 445 1.90 23.88	
60 435 2.5 23.61	
65 410 2.5 21.83	
67 385 2.6 20.92	
72 370 2.7 19.59	
76 345 2.8 18.62	
80 335 2.9 17.68	
S32A DM112M4 IE2	54
S32B DM112M4 IE2	54
S32C DM112M4 IE2	56
34 720 0.85 41.28	
38 650 0.90 37.12	
42 595 1.00 33.58	
46 545 1.05 30.61	
52 490 1.15 27.31	
58 440 1.25 24.49	
63 410 1.30 22.44	
63 400 1.35 22.22	
70 375 1.40 20.18	
72 355 1.45 19.69	
77 340 1.55 18.26	
81 315 1.55 17.33	
85 310 1.70 16.64	
93 275 1.70 15.18	
106 280 1.85 14.85	
106 245 1.85 13.33	
106 250 2.00 13.32	
117 230 2.1 12.08	
132 200 2.3 10.71	
150 179 2.5 9.43	
171 158 2.7 8.25	
194 138 2.9 7.25	
S22A DM112M4 IE2	43
S22B DM112M4 IE2	43
S22C DM112M4 IE2	45
91 285 0.95 15.50	
102 255 1.05 13.82	
114 230 1.10 12.40	
125 210 1.20 11.27	
142 186 1.30 9.94	
160 165 1.45 8.80	
179 149 1.55 7.88	
206 130 1.70 6.85	

Type		~kg
n2 [1/min]	T2 [Nm]	cG i

4.0 kW

S42A DM112MX4 IE2	71
S42B DM112MX4 IE2	71
S42C DM112MX4 IE2	75
30 1130 1.20 48.05	
33 1030 1.30 43.65	
36 950 1.30 39.91	
40 855 1.45 35.81	
44 780 1.55 32.32	
48 720 1.60 29.75	
54 645 1.75 26.59	
54 645 1.35 26.29	
60 590 1.45 23.88	
60 575 1.90 23.61	
65 540 1.85 21.83	
68 510 2.00 20.92	
73 485 2.1 19.59	
77 455 2.1 18.62	
81 440 2.2 17.68	
S32A DM112MX4 IE2	54
S32B DM112MX4 IE2	54
S32C DM112MX4 IE2	56
47 720 0.80 30.61	
52 645 0.85 27.31	
58 580 0.95 24.49	
64 530 1.00 22.22	
71 490 1.05 20.18	
72 470 1.10 19.69	
78 450 1.15 18.26	
82 415 1.20 17.33	
86 410 1.25 16.64	
94 365 1.30 15.18	
96 365 1.40 14.85	
107 325 1.40 13.33	
107 330 1.50 13.32	
118 300 1.60 12.08	
133 265 1.75 10.71	
151 235 1.90 9.43	
173 210 2.0 8.25	
197 183 2.2 7.25	
S22A DM112MX4 IE2	89
S22B DM112MX4 IE2	89
S22C DM112MX4 IE2	92
41 1160 1.10 35.81	
45 1050 1.15 32.32	
49 970 1.20 29.75	
55 870 1.30 26.59	
62 775 1.40 23.61	
70 685 1.45 20.92	
74 655 1.50 19.59	
78 610 1.55 18.62	
82 595 1.65 17.68	
89 550 1.90 16.28	
91 525 1.70 15.95	
100 490 2.0 14.55	
103 465 1.75 14.07	
113 435 2.1 12.92	
127 390 2.3 11.45	
143 350 2.4 10.19	
167 300 2.6 8.73	
189 265 2.7 7.70	


Type		~kg
n2 [1/min]	T2 [Nm]	cG i

7.5 kW


S42A DA132MX4 IE2	95
S42B DA132MX4 IE2	95
S42C DA132MX4 IE2	99
41 1580 0.80 35.81	
45 1430 0.85 32.32	
49 1320 0.85 29.75	
55 1180 0.95 26.59	
62 1060 1.00 23.61	
70 935 1.10 20.92	
74 895 1.10 19.59	
78 835 1.15 18.62	
82 810 1.20 17.68	
89 745 1.40 16.28	
91 715 1.25 15.95	
100 670 1.50 14.55	
103 635 1.30 14.07	
113 595 1.60 12.92	
127 530 1.65 11.45	
143 475 1.75 10.19	
167 410 1.90 8.73	
189 360 2.0 7.70	

Dimensions


A - Foot mounted version



	A	AB	A1	A2	A3	B	B1	B2	H	HA	HB	H1	H2	H3	H4	H5	L	S1
S0	50	63	86	43	2	60	52-0.5	30	70-0.5	9	9	7.5	113	106.5	29	86	126	M6
S1	90	110	116	58	2	75	70-0.5	37.5	95-0.5	15	12	10	151.5	137.5	30	95	160	Ø9
S2	110	135	144	72	3	90	85-0.5	45	120-0.5	18	15	18	191	175	40	120	191	Ø11
S3	120	150	168	84	3.5	115	100-0.5	57.5	145-0.5	22	18	24	229.5	212	47	150	233	Ø13.5
S4	150	185	202	101	4	135	125-0.5	70	180-0.5	25	22	35	280	259.5	57	180	280	Ø17.5


B - Shaft mounted version

	A1	A2	A3	B3	H1	H6	H7	L1	M1	P1	S2	T2
S0	86	43	2	52	7.5	113.5	70.5	126	74	86	M6	9
S1	116	58	2	69	10	153.5	97	159	87	99	M6	9
S2	144	72	3	85	18	193	122	191	96	112	M8	12
S3	168	84	3.5	100	24	231.5	147	233	106	122	M8	12
S4	202	101	4	125	35	282	182	280	130	150	M10	15


C - Flange mounted version

	A2	A3	A4	B3	B7	H1	H6	H7	L1
S0	43	2	63	52	18	7.5	113.5	70.5	126
S1	58	2	70	69	10	10	153.5	97	159
S2	72	3	83	85	8	18	193	122	191
S3	84	3.5	95	100	7.5	24	231.5	147	233
S4	101	4	113	125	8	35	282	182	280

	M	N	P	LA	T	S
S0	Ø100	Ø80 j6	Ø120	8	3	Ø6.6
S1	Ø130	Ø110 j6	Ø160	9	3.5	Ø9
S2	Ø165	Ø130 j6	Ø200	10	3.5	Ø11
S3	Ø165	Ø130 j6	Ø200	10	3.5	Ø11
S4	Ø215	Ø180 j6	Ø250	11	4	Ø13.5

D - Shaft mounted version + foot area


	A1	A2	A3	A5	B3	B4	B5	B6	H	H1	H2	L1	M1	P1	S2	T2	S3	T3
S1	116	58	2	50	69	46	82	54	95	10	151.5	159	87	99	M6	9	M8	12
S2	144	72	3	65	85	58	110	54	120	18	191	191	96	112	M8	12	M8	12
S3	168	84	3.5	70	100	67.5	135	65.5	145	24	229.5	233	106	122	M8	12	M10	15
S4	202	101	4	80	125	87.5	175	67.5	180	35	280	280	130	150	M10	15	M16	24

E - Flange mounted version + foot area

	A2	A3	A4	A5	B3	B4	B5	B6	B7	H	H1	H2	L1	S3	T3
S1	58	2	70	50	69	46	82	54	10	95	10	151.5	159	M8	12
S2	72	3	83	65	85	58	110	54	8	120	18	191	191	M8	12
S3	84	3.5	95	70	100	67.5	135	65.5	8	145	24	229.5	233	M10	15
S4	101	4	113	80	125	87.5	175	67.5	8	180	35	280	280	M16	24


M	N	P	LA	T	S
S1	Ø130	Ø110 j6	Ø160	9	3.5 Ø9
S2	Ø165	Ø130 j6	Ø200	10	3.5 Ø11
S3	Ø165	Ø130 j6	Ø200	10	3.5 Ø11
S4	Ø215	Ø180 j6	Ø250	11	4 Ø13.5

Hollow shaft with keyway




	A8	D1	D2	E3	E4	E5	F1	G1
S0	45	$\varnothing 20\text{H}7$	35	90	14	-	6	22.8
S1	60	$\varnothing 25\text{H}7$	45	120	15	-	8	28.3
S2	75	$\varnothing 30\text{H}7$ $\varnothing 35\text{H}7$	50	150	18	-	8 10	33.3 38.3
S3	87.5	$\varnothing 40\text{H}7$	55	175	20	-	12	43.3
S4	105	$\varnothing 50\text{H}7$	70	210	25	70	14	53.8


V - Output shaft with key



	A6	D	DB	E	E1	E2	F	GA
S02A	85							
S02C	103	$\varnothing 20\text{k}6$	M6	40	32	4	6	22.5
S1	120	$\varnothing 25\text{k}6$	M10	50	40	5	8	28
S2	143	$\varnothing 30\text{k}6$	M10	60	50	5	8	33
S3	153	$\varnothing 35\text{k}6$	M12	70	60	5	10	38
S4	175	$\varnothing 40\text{k}6$	M16	80	70	5	12	43
	213	$\varnothing 50\text{k}6$	M16	100	80	10	14	53.5

S - Hollow shaft with shrink disc

	A7	A8	D2	D3	D5	D6	E6	E7	E8
S1	97	60	45	77	Ø25H7	Ø25H6	143	25	27
S2	113	75	50	86	Ø30H7 Ø35H7	Ø30h6 Ø35h6	176	30	32
S3	127	87.5	55	96	Ø40H7	Ø40h6	202	40	42
S4	150	105	70	117	Ø50H7	Ø50h6	242	50	52

T1 - Torque arm

	A9	A10	A11	A12	D11	D12	H8	R1	R2
S0	52.5	15	47	4	11	32	100	20	43
S1	68.5	15	64	6	11	32	130	20	49.5
S2	87	22	80	8	11	32	160	20	56
S3	99	22	92	8	11	32	200	23	61
S4	121	32	109	8	17	40	250	30	75